1/23463/2022

File No. FReing Freing PB-1/0/(1/2022-Mer No. 7109)

पत्तन,पोत परिवहन और जलमार्ग मंत्रालय Ministry of Ports, Shipping and Waterways

दीपस्तंभ और दीपपोत निदेशालय, पोर्ट ब्लेयर



Directorate of Lighthouses and Lightships, Port Blair

EM-PB-10/1/2022-M

Date:16/09/2022

Fron	n: THE DIRECTOR, PORT BLAIR	FAX NO: 03192-244577	dte-port@gv.in
To:	THE CHIEF HYDROGRAPHER DEHRADUN	FAX NO: 0135-2748373	msis-inho-navy@nic.in
	THE OFFICER INCHARGE, NAVAL CHART DEPOT, MUMBAI	FAX NO: 022-22751049	ncdm-inho-navy@nic.in
	THE DGLL NOIDA	FAX NO:0120-2411345	noida-dgll@nic.in

EAST ISLAND RACON, CODE 'D' FREQUENCY BAND 'X' IS NON OPERATIONAL FROM 13/09/2022 (.) INFORM MARINERS (.) DEEP SENT (.) COAST SENT (.)

-sd-कृते निदेशक /FOR DIRECTOR

पुष्टि के लिए डाक द्वारा प्रतिलिपि अग्रेषित

- मुख्य हाइड्रोग्राफर, भारत सरकार, नौसेना हाइड्रोग्राफिक अधिकारी, पोस्ट बॉक्स नंबर 75, 107-ए राजपुर नगर, देहरादून - 248001 (उत्तराखंड)।
- 2. अधिकारी प्रभारी, नौसेना चार्ट डिपो, कैसल पार्क, शहीद भगत सिंह रोड, मुंबई 4000231

प्रतिलिपि केवल महानिदेशक हेतु अग्रेषित:

 महानिदेशक , दीपस्तंभ और दीपपोत महानिदेशालय नोएडा। - Racon was found Non- operational and on further inspection it was found that crack has developed on the chassis due to aiging and water has clogage in the base of RACON, process of repair/rectification is being processed through OEM.

कृते निदेशक / For Director